



### CODE ENFORCEMENT BOARD HEARING AGENDA

### JANUARY 28, 2020 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

### CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.\_

PLEASE NOTE THAT TWO-WAY COMMUNICATION BETWEEN MEMBERS OF THE BOARD IS PROHIBITED BY SUNSHINE LAW. PLEASE DO NOT REPLY TO ANY BOARD MEMBER. ALL DISCUSSIONS ON RELEATIVE TO THE AGENDA SHOULD TAKE PLACE AT SCHEDULED BOARD MEETINGS.

Two or more City Commissioners and/or Advisory Board members may be present at this meeting. If a person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing, he/she will need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

If you desire auxiliary services to assist in viewing or hearing the meetings or reading agendas and minutes for the meetings, please contact the City Clerk's office at (954) 828-5002 and arrangements will be made to provide these services for you.

Unless otherwise stated, these items are quasi-judicial. Board members shall disclose any communication or site visits they have had pursuant to Section 47-1.13 of the ULDR. All persons speaking on a quasi-judicial matter will be sworn in and will be subject to cross-examination.

Board Members: Patrick McGee, Chair • Mark Booth, Vice Chair • Julie Lurie

- Peter Cooper Chris Evert William Marx Justin Beachum Terry Nolen (alternate)
- Michael Madfis (alternate) Lahki Mohnani (alternate) Board Attorney: Bruce Jolly

.....

#### **NEW BUSINESS**

\_\_\_\_\_\_

CASE NO: CE17051026

CASE ADDR: 327 SW 12 AVE
OWNER: ESPOSITO, ROBERT
ESPOSITO, ENRICO

INSPECTOR: JOSE SARAGUSTI

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK LLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. BRICK PAVERS INSTALLED WITHOUT OBTAINING PERMITS AND INSPECTIONS.
- 2. PAVERS INSTALLED IN SWALE AREAS.

\_\_\_\_\_\_

CASE NO: CE18070643

CASE ADDR: 1522 NE 4 AVE OWNER: SANZERI, CONNIE SANZERI, JOSEPH C

INSPECTOR: JOSE SARAGUSTI

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CHANGE OF USE.
- 2. PAVERS.
- 3. HURRICANE SHUTTERS.
- 4. MECHANICAL.
- 5. ELECTRIC.
- 6. PLUMBING.
- 7. DEMOLITION OF OFFICE SPACE.

-----

CASE NO: CE19030312

CASE ADDR: 3720 SW 22 ST OWNER: BUSTILLO, MARIANA Z INSPECTOR: JOSE SARAGUSTI

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK LLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND NSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CONCRETE DRIVEWAY.
- 2. GAZABO BUILT IN THE REAR OF THE PROPERTY.

CASE NO: CE19060880 CASE ADDR: 1017 SW 4 ST

OWNER: VIGIL, PAUL

INSPECTOR: JOSE SARAGUSTI

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WINDOWS REMOVED FROM THE EAST SIDE OF THE RESIDENCE AND OPENINGS ENCLOSED.

-----

CASE NO: CE19091491

CASE ADDR: 1351 SW 32 ST OWNER: SERRA, DAVID

INSPECTOR: JOSE SARAGUSTI

VIOLATIONS:FBC(2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW KITCHEN CABINETS.

- 2. KITCHEN PLUMBING, SINK AND FAUCET.
- 3. KITCHEN OUTLETS.

4. NEW TANK-LESS WATER HEATER AND ELECTRICAL.

-----

CASE NO: CE19051240

CASE ADDR: 1952 NW 9 AVE

OWNER: SUNTRAX CORP

% HADIGA HAIDER

INSPECTOR: LEONARDO MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. STRUCTURE BUILT IN THE REAR OF PROPERTY ENCROACHING THE SETBACK.

CASE NO: CE19091233

CASE ADDR: 1320 NW 19 ST OWNER: LAKES, PARRIS H/E

WILLIAMS, SHENIQUA L INSPECTOR: LEONARDO MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WOOD FENCE.

- 2. WINDOWS.
- 3. DOORS.
- 4. BUILDING BUILT IN THE REAR OF THE PROPERTY.

\_\_\_\_\_\_

CASE NO: CE19061178

CASE ADDR: 3120 SW 14 ST OWNER: STEVENS, JESSE C

INSPECTOR: LEONARDO MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK LLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND NSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REMODELED KITCHEN AND TWO BATHROOMS.
- 2. NEW ELECTRICAL PANEL, ELECTRICAL SWITCHES, INDOOR AND DOOR OUTLETS.
- 3. PLUMBING FOR BATHROOMS, AND KITCHEN.
- 4. GAS LINES FOR HOTWATER HEATER, DRYER, AND STOVE.

-----

CASE NO: CE19062280
CASE ADDR: 1745 NE 52 ST
OWNER: KNEZEVICH, DAVID

INSPECTOR: LEONARDO MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. BATHROOM AND KITCHEN RENOVATION.
- 2. CONVERTED TWO ROOMS INTO A KITCHEN.

VIOLATIONS: FBC (2017) 111.1.1

THE USE AND THE OCCUPANCY OF THIS PARCEL AND BUILDING HAVE BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY RESIDENT WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

\_\_\_\_\_\_

CASE NO: CE19100334

CASE ADDR: 1516 NE 16 AVE

OWNER: NICKEL, ANTHONY & ELIZABETH

INSPECTOR: LEONARDO MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK LLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND NSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WOOD FENCE INSTALLED WITHOUT A PERMIT.

------

CASE NO: CE19050650

CASE ADDR: 113 SW 21 WAY

OWNER: US HOUSING EQUITY FUND LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DOORS AND WINDOWS REPLACEMENT & DOOR ENCLOSURE.

\_\_\_\_\_\_

CASE NO: CE19081023 CASE ADDR: 342 SW 22 ST

OWNER: KAPAKOS, CONSTANTINOS INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR RENOVATION: STRUCTUAL, ELECTRICAL, PLUMBING.
- 2. REPLACED FRONT PORCH ROOF JOIST.

CASE NO: CE19081560

CASE ADDR: 2900 BANYAN ST, #602

OWNER: HOVATER, DAVID B INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF AN A/C UNIT WITH A/C DUCTS.

\_\_\_\_\_

#### RETURN HEARING (OLD BUSINESS)

\_\_\_\_\_\_

CASE NO: CE15050755
CASE ADDR: 1200 NW 9 ST
OWNER: ASSIS HOMES LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. SINGLE FAMILY RESIDENCE CONVERTED INTO A DUPLEX.

VIOLATIONS: FBC (2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

------

CASE NO: CE16051422

CASE ADDR: 1249 SEABREEZE BLVD OWNER: MITTONE, PATRICIA & HUGO INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING INCLUDING KITCHEN AND BATHROOMS.
- 2. TILED WALL COVERINGS IN BATHROOMS AND KITCHENS INCLUDING BUT NOT LIMITED TO WET AREAS.

### VIOLATIONS: FBC (2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WATER SUPPLY AND WASTE LINES.
- 2. INSTALLATION OF BATHROOM AND KITCHEN FIXTURES NOT LIMITED TO SINKS, FAUCETS, VANITIES, TOILETS AND BIDETS.
- 3. INSTALLATION OF WATER HEATER.

#### VIOLATIONS: FBC (2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WIRING CIRCUITS.
- 2. INSTALLATION OF ELECTRICAL FIXTURES.
- 3. INSTALLATION OF BREAKER PANELS.
- 4. INSTALLATION OF NEW LIGHTING.
- 5. INSTALLATION OF NEW RECEPTACLES.

REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D) (1) THRU (D) (6) GFI'S REQUIRED AS PER NEC 108.8 OUTLET SPACING AS REQUIRED UNDER NEC 210.52.

VIOLATIONS: FBC (2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. REPLACEMENT OF MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK AND REGISTERS.

#### VIOLATIONS: FBC (2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLATION AND REPLACEMENT OF DOORS AND WINDOWS.

### VIOLATIONS: FBC (2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

#### VIOLATIONS: FBC (2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

### VIOLATIONS: FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16121959

CASE ADDR: 1524 SW 18 TER OWNER: MINEO, CHARLES H/E

MINEO, JANET H

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CONSTRUCTED 3RD BEDROOM ADDITION CHANGING FLOOR PLAN FROM A 2 BEDROOM 1 BATH TO A 3 BEDROOM 2 BATH.
- 2. CONSTRUCTED ROOF OVER FRONT PORCH.
- 3. ENCLOSED CARPORT.
- 4. CONSTRUCTED STORAGE ATTIC IN ILLEGALLY ENCLOSED CARPORT.
- 5. CONSTRUCTED KITCHEN ADDITION.
- 6. INSTALLED HURRICANE STORM PANELS.
- 7. REPLACED FRONT DOOR.
- 8. INSTALLED SGD TO ENCLOSED SCREENED SUNROOM.
- 9. ALTERING, MODIFYING AND NEW WORK IN THE BUILDING SYSTEM REQUIRING PERMITS FROM SEVERAL DISCIPLINES.

VIOLATIONS: FBC (2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE18061230

CASE ADDR: 6701 NW 21 TER

OWNER: HERNANDEZ, KEITH & NICOLE

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2017) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK

1. NEW FENCE INSTALLED IN FRONT AND SOUTH ELEVATIONS OF THE PROPERTY.

CASE NO: CE18111242

CASE ADDR: 1426 NE 60 ST

OWNER: PALAU INC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. NEW BOAT DOCK INSTALLED OVER EXISTING DOCK.
- 2. TIKI HUT INSTALLED WITHOUT ZONING PERMIT.
- 3. NEW A/C CONDENSER UNIT INSTALLED.
- 4. WOOD TRELLIS INSTALLED ABOVE FRONT ENTRANCE.

\_\_\_\_\_\_

CASE NO: CE19031344

CASE ADDR: 820 NE 17 AVE OWNER: V P NE 17TH AVE LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING AND FRANMING.
- 2. NEW PAVERS INSTALLED.
- 3. NEW PLUMBING INSTALLATION IN KITCHEN AND BATHROOMS.
- 4. NEW EXTERIOR ELECTRICAL INSTALLATION.
- 5. NEW ELETRICAL PANEL AND OUTLETS.
- 6. A/C INSTALLED.
- 7. NEW DOORS AND FRAMES.
- 8. NEW WINDOWS.
- 9. DOORS AND WINDOWS ENCLOSURE.

### VIOLATIONS: FBC (2017) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

CASE NO: CE19031345

CASE ADDR: 828 NE 17 AVE OWNER: V P NE 17TH AVE LLC INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING AND FRAMING.
- 2. NEW PLUMBING INSTALLATION (FIXTURES AND PIPE).
- 3. NEW ELECTRICAL INSTALLATION.
- 4. NEW PAVERS INSTALLED.
- 5. NEW DOORS AND WINDOWS.

#### VIOLATIONS: FBC (2017) 110.2

(RIGHT TO INSPECT) BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

\_\_\_\_\_\_

CASE NO: CE18060407 CASE ADDR: 1422 NW 2 ST

OWNER: LEO F WEBER REAL ESTATE

INVESTMENT LLC

INSPECTOR: LEONARDO MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO: INTERIOR RENOVATIONS:

- 1. TWO BATROOMS INCLUDING PLUMBING, ELECTRICAL AND MECHANICAL VENTS.
- 2. INTERIOR OFFICE RENOVATED INCLUDING DRYWALLING THE CEILING, NEW LIGHT FIXTURES, NEW OUTLETS AND SWITCHES, DRYWALL ON THE SOUTH WALL.
- 3. NEW PASS THRU OPENING CUT IN SOUTH PARTITION WALL.

CASE NO: CE17020146
CASE ADDR: 1545 NW 6 ST
OWNER: PERSAUD, BOODHWATTIE
INSPECTOR: LEONARDO MARTINEZ

VIOLATIONS: FBC (2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. INSTALLATION OF SINKS.

2. INSTALLATION OF GAS LINES TO SERVICE GAS STOVES.

### VIOLATIONS: FBC (2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS: 1.

ADDED OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH NEC 406.4 (D) (1) THRU (D) (6) GFI? S REQUIRED AS PER NEC 108.8 OUTLET SPACING AS REQUIRED UNDER NEC 210.52 R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

#### VIOLATIONS: FBC (2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLED FIRE SUPPRESSION SYSTEM WITH HOOD.

### VIOLATIONS: FBC (2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

#### VIOLATIONS: FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

### VIOLATIONS: FBC (2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS PARCEL AND BUILDING HAVE BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF BEAUTY SALON TO RESTAURANT WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE17020835

CASE ADDR: 1000 SW 18 CT OWNER: SOJA, WIESLAW

INSPECTOR: LEONARDO MARTINEZ

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. WINDOWS AND DOORS REPLACEMENT.
- 2. MODIFICATION OF SOME EXTERIOR OPENINGS.

VIOLATIONS: FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE17080931 CASE ADDR: 480 NW 17 PL OWNER: NELFORT, MARIE R

INSPECTOR: LEONARDO MARTINEZ

VIOLATIONS : FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REAR ADDITION ADDED WITHOUT A PERMIT.

-----

CASE NO: CE19011949
CASE ADDR: 3427 SW 12 CT
OWNER: SNI PROPERTIES LLC
INSPECTOR: LEONARDO MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CARPORT ENCLOSURE WITHOUT A PERMIT.

CASE NO: CE18010886

CASE ADDR: 1000 NW 52 ST OWNER: REISS, STEVEN D NSPECTOR: JORGE MARTINEZ

VIOLATIONS : FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. TOTAL RENOVATION/DEMOLITION. INCLUDES DRYWALL, PLUMBING, ELECTRICAL BLOCKED UP OPENINGS AND WINDOWS INSTALLED ALL WITHOUT BEING PERMITTED.

VIOLATIONS:FBC(2014) 110.6 FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

\_\_\_\_\_\_

CASE NO: CE17101744

CASE ADDR: 3000 TERRAMAR ST OWNER: NORTH BEACH HOTEL LLC INSPECTOR: JORGE MARTINEZ

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. DEMOLITION OF POOL BATHHOUSE.
- 2. BREACH OF FIRE WALLS IN POOL BATHHOUSE.
- 3. WINDOWS AND DOORS INSTALLED.

#### VIOLATIONS: FBC (2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND DEMOLITION WORK HAS BEEN PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. POOL BATHHOUSE INTERIOR DEMOLITION.
- 2. BREACH FIRE PARTITION BY REMOVAL OF DRYWALL IN POOL BATHHOUSE.

### VIOLATIONS: FBC (2014) 110.2

BEFORE ISSUING A PERMIT, THE BUILDING OFFICIAL IS AUTHORIZED TO EXAMINE OR CAUSE TO BE EXAMINED BUILDINGS, STRUCTURES AND SITES FOR WHICH AN APPLICATION HAS BEEN FILED.

CASE NO: CE18020982 CASE ADDR: 515 NW 7 TER OWNER: BARR, ESSIE MAE

SMITH, EDWARD H EST INSPECTOR: JORGE MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WINDOWS AND DOORS INSTALLED WITHOUT A PERMIT.

VIOLATIONS: FBC (2017) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTIONS BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES.

------

CASE NO: CE18040661

CASE ADDR: 300 SW 31 AVE OWNER: DIXON, CARLTON A INSPECTOR: JORGE MARTINEZ

VIOLATIONS: FBC (2017) 116.1.1

BUILDINGS OR STRUCTURES THAT IN THE OPINION OF THE BUILDING OFFICIAL ARE, OR HEREAFTER SHALL BECOME UNSAFE, UNSANITARY OR DEFICIENT IN ADEQUATE FACILITIES FOR MEANS OF EGRESS, OR WHICH CONSTITUTE A FIRE OR WINDSTORM HAZARD, OR ILLEGAL OR IMPROPER USE, OCCUPANCY OR MAINTENANCE, OR WHICH DO NOT COMPLY WITH THE PROVISIONS OF THE APPLICABLE MINIMUM HOUSING CODE, OR WHICH HAVE BEEN SUBSTANTIALLY DAMAGED BY THE ELEMENTS, ACTS OF GOD, FIRE, EXPLOSION OR OTHERWISE SHALL BE DEEMED UNSAFE BUILDINGS AND A PERMIT SHALL BE OBTAINED TO DEMOLISH THE STRUCTURE OR BRING THE BUILDING TO COMPLY WITH THE APPLICABLE CODES.

CASE NO: CE18080550

CASE ADDR: 311 FLORIDA AVE

OWNER: TAPIA, MARIA M INSPECTOR: JORGE MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR PARTITION.
- 2. KITCHEN RENOVATION.
- 3. INSTALLING NEW BATH.
- 4. ELECTRICAL FOR A/C COMPRESSOR.
- 5. LAUNDRY ROOM.
- 6. ROOM ADDITION.

-----

CASE NO: CE18081115
CASE ADDR: 101 SE 19 ST
OWNER: CHIMERA HOLDINGS LLC
INSPECTOR: JORGE MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CHANGE OF USE AND OCCUPANCY.
- 2. INTERIOR ALTERATIONS AND RECONFIGURATIONS.
- 3. FENCE WORK.
- 4. PLUMBING WORK.
- 5. MECHANICAL DUCT.
- 6. NEW A/C SYSTEM.
- 7. CANOPY STRUCTURE AT THE ENTRY AREA.
- 8. ELECTRICAL UPGRADE.
- 9. NEW SPRINKLER PUMP AND TIMER INSTALLATION.

CASE NO: CE18101875

CASE ADDR: 532 SW 10 AVE OWNER: ROMERO, MICHAEL INSPECTOR: JORGE MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. EXTENDED CONCRETE DECK OVER THE SEAWALL.
- 2. REAR WOOD FENCE.
- 3. NEW AC UNIT.
- 4. NEW KITCHEN SINK, TWO BATHROOMS REMODELED WITH NEW SINKS AND COMMODE.
- 5. EXHAUST VENT OVER THE STOVE.

-----

CASE NO: CE17101770

CASE ADDR: 550 N BIRCH RD OWNER: NORTH BEACH HOTEL LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK LLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR RENOVATION TO INCLUDE: DRYWALL PLUMBING, AND ELECTRICAL WORK.

VIOLATIONS: FBC (2014) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTIONS BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION PURPOSES UNTIL APPROVED.

VIOLATIONS: FBC (2014) 110.2

BEFORE ISSUING A PERMIT, THE BUILDING OFFICIAL IS AUTHORIZED TO EXAMINE OR CAUSE TO BE EXAMINED BUILDINGS, STRUCTURES AND SITES FOR WHICH AN APPLICATION HAS BEEN FILED.

CASE NO: CE18110574
CASE ADDR: 901 SE 14 ST
OWNER: DERLLY, KAREN
INSPECTOR: BOBBY MASULA

VIOLATIONS: 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. NEW KITCHEN INSTALLED WITH PLUMBING, ELECTRIC, DRYWALL.
- 2. NEW WINDOWS INSTALLED.

3. NEW MINI SPLIT.

------

CASE NO: CE19030191

CASE ADDR: 5440 NW 33 AVE, # 113

OWNER: MERIDIAN REALTY PROPERTY WAREHOUSES

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

- 1. INTERIOR ALTERATIONS OF WALLS AND FLOOR PLAN INCLUDING FRAMING AND DRYWALL.
- 2. ELECTRICAL WORK FOR NEW WALLS AND 220V INSTALLED FOR WASHER AND DRYER.
- CHANGE OF USE BASED ON USE AND OCCUPANCY. THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

-----

CASE NO: CE19031519

CASE ADDR: 4820 NE 26 AVE

OWNER: 26TH LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

1. THE PROPERTY HAS BEEN COMPLETELY REMODELED WITH INTERIOR ALTERATIONS, KITCHEN AND BATHROOM REMODEL, FRAMING AND DRYWALL, ELECTRICAL, MECHANICAL AND PLUMBING WORK PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

VIOLATIONS: FBC (2017) 110.2

THIS PROPERTY WILL REQUIRE A FOLLOW UP SITE VISIT AND COMPLETE INSPECTION OF THE PROPERTY TO DETERMINE EXACTLY WHAT WORK HAS OR HAS NOT BEEN PERFORMED. PLEASE CONTACT ME TO SCHEDULE AN INSPECTION AS SOON AS POSSIBLE. ROBERT MASULA 954-828-5292.

-----

CASE NO: CE19040882

CASE ADDR: 1400 NE 16 CT OWNER: MDR MOTORS LLC

%MICHAEL GRIECO JR INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

 ALTERATIONS MADE SUCH AS A LARGE OFFICE TRAILER PLACED ON THIS PROPERTY WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE19041187

CASE ADDR: 1207 CORDOVA RD OWNER: VELOCITY 3 LLC INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

- 1. NEW FENCE INSTALLED ON THE PROPERTY.
- 2. THE A/C SYSTEM WAS REPLACED. THE DUCT WORK THROUGHOUT THE HOUSE HAS BEEN REPLACED AND IS NOT A CONVENTIONAL A/C DUCT SYSTEM.
- 3. THERE HAVE BEEN ELECTRICAL ALTERATIONS MADE TO THIS PROPERTY:
  - A. THE EXTERIOR ELECTRICAL PANEL WAS REPLACED.
  - B. THERE ARE BETWEEN 38 TO 40 HI-HAT LIGHT FIXTURES IN THIS HOUSE. THERE IS NO PERMIT RECORD FOR THESE HI-HAT LIGHT FIXTURES.
- 4. THE KITCHEN AND TWO BATHROOMS HAVE BEEN COMPLETELY REMODELED INCLUDING REMOVING AND REPLACING ALL THE PLUMBING FIXTURES. THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

VIOLATIONS: FBC (2017) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

\_\_\_\_\_\_

CASE NO: CE19051349

CASE ADDR: 1309 NE 1 AVE OWNER: WINNER, GARRETT E INSPECTOR: BOBBY MASULA

VIOLATIONS : FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

1. A LARGE WOOD DECK/STRUCTURE BEING BUILT WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE19060406

CASE ADDR: 2701 E COMMERCIAL BLVD OWNER: OCEAN REALTY ASSOCIATES LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

- 1. ELECTRICAL WORK.
- 2. CHANGE OF USE: FROM MERCANTILE GROUP TO AN ASSEMBLY GROUP PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS

-----

CASE NO: CE19060822 CASE ADDR: 300 SW 12 ST

OWNER: REILLY RYAN INVESTMENT GROUP LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS : FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

- 1. EXTENSIVE INTERIOR AND EXTERIOR DEMOLITION WITHOUT THE REQUIRED PERMITS.
- NEW FORMWORK, STEEL RE-BAR AND CONCRETE BLOCK INSTALLED.
   THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE19061832 CASE ADDR: 1609 SE 2 CT

OWNER: LESLEE WILLIAMS WALKER REV TR WALKER, LESLEE WILLIAMS TRSTEE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

1. INTERIOR RENOVATIONS INCLUDING ELECTRICAL AND PLUMBING PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

CASE NO: CE19070588

CASE ADDR: 819 N FEDERAL HWY

OWNER: ACS 817 LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS : FBC (2017) 105.1

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

- 1. COMPLETE INTERIOR REMODEL.
- 2. ELECTRICAL.
- 3. PLUMBING.
- 4. MECHANICAL.
- 5. A POSSIBLE CHANGE OF USE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

\_\_\_\_\_\_

CASE NO: CE19070753

CASE ADDR: 211 SW 2 ST, # W OWNER: RIVERWALK CENTRE LTD INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

1. AN INTERIOR WALL, POSSIBLY A LOAD BEARING WALL HAS BEEN REMOVED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

### VIOLATIONS: FBC (2017) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

### VIOLATIONS: FBC (2017) 116.1.1

UNSAFE BUILDINGS OR STRUCTURES THAT IN THE OPINION OF THE BUILDING OFFICIAL ARE, OR HEREAFTER SHALL BECOME UNSAFE, UNSANITARY OR DEFICIENT IN ADEQUATE FACILITIES FOR MEANS OF EGRESS, OR WHICH CONSTITUTE A FIRE OR WINDSTORM HAZARD, OR ILLEGAL OR IMPROPER USE, OCCUPANCY OR MAINTENANCE, OR WHICH DO NOT COMPLY WITH THE PROVISIONS OF THE APPLICABLE MINIMUM HOUSING CODE, OR WHICH HAVE BEEN SUBSTANTIALLY DAMAGED BY THE ELEMENTS, ACTS OF GOD, FIRE, EXPLOSION OR OTHERWISE SHALL BE DEEMED UNSAFE BUILDINGS AND A PERMIT SHALL BE OBTAINED TO DEMOLISH THE STRUCTURE OR BRING THE BUILDING TO COMPLY WITH THE APPLICABLE CODES.

-----

CASE NO: CE19032219

CASE ADDR: 751 NW 57 ST, # 3 OWNER: 751 NW 57TH ST LLC INSPECTOR: BOBBY MASULA

VIOLATIONS:FBC(2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

- 1. CONVERTING A WAREHOUSE SPACE INTO A BAKERY. THIS WORK WILL REQUIRE A CHANGE OF USE.
- 2. THERE IS ELECTRICAL, MECHANICAL AND PLUMBING WORK THAT HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

\_\_\_\_\_

\_\_\_\_\_

### HEARING TO IMPOSE FINES

### CHAPTER 11, FORT LAUDERDALE CODE OF ORDINANCES

CASE NO: CE17060261

CASE ADDR: 1041 NE 9 AVE

OWNER: SELF DIRECTED IRA SERVICES INC JULIETA A HORNER IRA 201315701

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CONSTRUCTED AN ENCLOSED GARAGE.

2. BUILT FENCE.

\_\_\_\_\_\_

CASE NO: CE17071043

CASE ADDR: 6250 N ANDREWS AVE, #25

OWNER: DOUBLE MOUNTAIN DEV VENTURES LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND NSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR ALTERATIONS TO FLOOR PLAN.
- 2. INSTALLED ELECTRICAL.
- 3. INSTALLED BATHTUBS
- 4. INSTALLED WATER HEATERS.

VIOLATIONS: FBC (2014) 110.1

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE18102205

CASE ADDR: 430 FLORIDA AVE OWNER: DREAM HOMES LEASING LLC

INSPECTOR: JOSE SARAGUSTI

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REPLACED DOORS AND WINDOWS.
- 2. NEW COLUMN FRONT PORCH BEAM SUPPORT.
- 3. NEW FRONT PORCH LIGHTING.
- 4. NEW FLOOD LIGHTS EXTERIOR CORNERS.
- 5. REMODELED BATHROOMS AND KITCHEN.
- 6. A/C UNIT INSTALLED.
- 7. ELECTRICAL PANEL CHANGE OUT.
- 8. NEW HOT WATER HEATER.

\_\_\_\_\_\_

CASE NO: CE18061643 CASE ADDR: 931 NW 53 CT

OWNER: LORD PROPERTIES II LLC INSPECTOR: JOSE SARAGUSTI

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR ALTERATIONS/BUILDING INTERIOR OFFICE INSIDE A WAREHOUSE.
- 2. INSTALLING SECURITY/SURVEILLANCE CAMERA.
- 3. ELECTRICAL UPGRADE WORK.

CASE NO: CE18100735

CASE ADDR: 901 N BIRCH RD

OWNER: MARINE COLONY VILLAS CO-OP

INSPECTOR: JOSE SARAGUSTI

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLING A CBS TRASH ENCLOSURE WITHOUT A PERMIT.

CASE NO: CE17100827

CASE ADDR: 1243 NE 11 AVE OWNER: STEINBERGER, MARK INSPECTOR: BOBBY MASULA

VIOLATIONS : FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED

TO:

1. ALTERATIONS MADE SUCH AS AWNING STRUCTURE, INTERIOR ALTERATIONS, OUTSIDE PATIO BAR WITH ELECTRICAL, PLUMBING AND MECHANICAL WORK PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

VIOLATIONS :FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

-----

CASE NO: CE19021611

CASE ADDR: 4812 NE 23 AVE, #8

OWNER: COLLIS, GRAHAM

MALDONADO, BIANCA INSPECTOR: BOBBY MASULA

VIOLATIONS : FBC (2017) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO ALTERATIONS MADE SUCH AS:

- 1. KITCHEN HAS BEEN REMODELED INCLUDING REMOVING AN INTERIOR PARTITION, REMOVING AND REPLACING ELECTRICAL AND PLUMBING FIXTURES.
- 2. THE INTERIOR ELECTRICAL PANEL HAS BEEN REMOVED AND REPLACED.
- 3. THE A/C MECHANICAL UNIT HAS BEEN REMOVED AND REPLACED. ALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

VIOLATIONS :FBC(2017) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

CASE NO: CE18041516

CASE ADDR: 6301 NE 20 WAY OWNER: HOLLEY, STEVEN

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2017) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED

TO:

1. ALTERATIONS MADE SUCH AS REMOVING AND REPLACING A/C EQUIPMENT.

CASE NO: CE18041864

CASE ADDR: 2889 SW 16 ST OWNER: R S ROCHA LLC INSPECTOR: JORGE MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK LLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND NSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ATTACHED UTILITY SHED BUILT WITHOUT A PERMIT.

\_\_\_\_\_\_

CASE NO: CE18110066

CASE ADDR: 784 W EVANSTON CIR

OWNER: AUGUSTE, TONY

INSPECTOR: JORGE MARTINEZ

VIOLATIONS: FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ENCLOSURE OF THE GARAGE DOOR OPENING.
- 2. REPLACED 3' DOOR ON WEST SIDE OF THE GARAGE.
- 3. REPLACED WINDOW ON THE WEST SIDE OF THE GARAGE.

CASE NO: CE19022026

CASE ADDR: 1121 SW 19 ST OWNER: KARSKO, DANIEL INSPECTOR: JORGE MARTINEZ

VIOLATIONS : FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW INTERIOR WALL.

- 2. A/C UNIT CHANGEOUT.
- 3. ELECTRICAL PANEL REPLACED.

-----

CASE NO: CE19041534

CASE ADDR: 1109 NE 16 TER OWNER: CRICKETT, JOHN J INSPECTOR: JORGE MARTINEZ

VIOLATIONS : FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ILLEGAL CONVERSION OF A FOUR UNIT EFFICIENCY INTO A FIVE UNIT WITHOUT A PERMIT.
- 2. METER ROOM AND UTILITY ROOM MISSING DRYWALL ON FIRE SEPARATION WALL.
- 3. STRUCTURE ROOF BUILT OVER WASHING MACHINE AREA.
- 4. PLUMBING, ELECTRICAL AND DRAINAGE LINE FOR WASHING MACHINE.
- 5. REPLACED FRONT PORCH ROOF SUPPORT WITH 4X4 COLUMN SUPPORTS.

### VIOLATIONS : FBC (2017) 111.1.1

THE USE AND THE OCCUPANCY OF THIS PARCEL AND BUILDING HAVE BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY LASSIFICATION OF A FOUR UNIT EFFICIENCY WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE18010668
CASE ADDR: 835 NE 16 ST
OWNER: SUNSET TRUST

INSPECTOR: JORGE MARTINEZ

VIOLATIONS : FBC (2017) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. TWO UNPERMITTED UTILITY SHEDS. INSIDE ONE OF THE SHEDS:
  - A. HOT WATER HEATER.
  - B. WASHER AND DRYER.
  - C. ELECTRICAL AND PLUMBING.
- 2. A LARGE ROOF AND PATIO DECK BUILT WITHOUT A PERMIT.
- 3. VINYL FENCE SEPARATING THE MAIN HOUSE FROM A SEPARATE LIVING QUARTER, WITH A MAKESHIFT ROOF BUILT WITH 2X4'S AND A PLASTIC CORRUGATED ROOF.
- 4. THERE IS AN ELECTRICAL CORD COMING FROM THE ATTIC RUNNING BENEATH THE GROUND TO AN ELECTRICAL MOTORIZED GATE.
- 5. THERE IS A BATHROOM ADDITION AND NO PERMIT HISTORY.
- 6. THE GARAGE AND POSSIBLY ANOTHER AREA SEPARATED AND IS BEING USED AS LIVING QUARTERS. THIS PROPERTY WILL BE CITED FOR WORK WITHOUT A PERMIT AND ILLEGAL OCCUPANCY.
- 7. A/C UNIT INSTALLED (2014) NO PERMIT HISTORY.

### VIOLATIONS: FBC (2017) 110.1

CONSTRUCTION OR WORK FOR WHICH A PERMIT IS REQUIRED SHALL BE SUBJECT TO INSPECTIONS BY THE BUILDING OFFICIAL AND SUCH CONSTRUCTION OR WORK SHALL REMAIN ACCESSIBLE AND EXPOSED FOR INSPECTION.

### VIOLATIONS: FBC (2014) 110.2

BEFORE ISSUING A PERMIT, THE BUILDING OFFICIAL IS AUTHORIZED TO EXAMINE OR CAUSE TO BE EXAMINED BUILDINGS, STRUCTURES AND SITES FOR WHICH AN APPLICATION HAS BEEN FILED.

### VIOLATIONS :FBC (2017) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THEORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF SINGLE FAMILY WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE18120956

CASE ADDR: 701 NW 19 ST, # 112

OWNER: HERMAN, KATIA ALVES DE CAMPOS

HERMAN, MICHAEL

INSPECTOR: LEONARDO MARTINEZ

VIOLATIONS: 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. DEMOLITION OF MASTER BATHROOM.
- 2. RELACEMENT OF ELECTRICAL OUTLETS THROUGHOUT AND REWIRED INSIDE WALLS.
- 3. ENLARGEMENT OF OPENING INTO THE KITCHEN AND ALCOVE OF LIVING ROOM.
- 4. REPLACEMENT OF WATER HEATER.